

## **EASA Certification Information**

No.: 2015-01

Issued: 05 January 2015

Subject: Transfer of Supplemental Type Certificates from UNI AIR to Business and

**Commuter Aircraft** 

Supplemental Type Certificate No: EASA.A.S.03350 (10015037), 10041337, 10038465, EASA.A.S.03669 (10015241), EASA.A.S.03349 (10015036), EASA.A.S.03008 (10014805), EASA.A.S.03215 (10014951), EASA.A.S.03546 Rev1 (10015172), 10031744, EASA.A.S.00306 Rev1 (10031335), 10039277

**Issued by**: European Aviation Safety Agency

Former Holder of the Certificate: UNI AIR,

EASA AP DOA ref: EASA.AP080

**New Holder of the Certificate:** Business and Commuter Aircraft,

EASA AP DOA ref: EASA.AP072

## **Background:**

Business and Commuter Aircraft has made an application, dated 30 April 2014 to EASA for the transfer of the following Supplemental Type Certificates (STC) to Business and Commuter Aircraft:

- 1. **STC EASA.A.S.03350 (10015037)** Installation of an In-Flight Passenger Entertainment System in cabin applicable to Dassault Aviation MF50 aircraft.
- 2. **STC 10041337** Installation of Iridium Satcom System ICS-120B applicable to Dassault Aviation MF900 aircraft.
- 3. **STC 10038465** Enhanced Mode "S" compliance upgrade applicable to Dassault Aviation MF50 aircraft.
- 4. **STC EASA.A.S.03669 (10015241)** Iridium telecommunication system installation applicable to Dassault Aviation MF50 aircraft.
- 5. **STC EASA.A.S.03349 (10015036)** Installation of 220 VAC Electrical Power Supply and Distribution in Cabin applicable to Dassault Aviation MF50 aircraft.
- 6. **STC EASA.A.S.03008 (10014805)** Cabin Interior Refurbishment applicable to Dassault Aviation Falcon 20-E5 aircraft.
- 7. **STC EASA.A.S.03215 (10014951)** Antenna and Cables Installation provisions for satellite communication system applicable to Dassault Aviation MF50 aircraft.
- 8. **STC EASA.A.S.03546 Rev1 (10015172)** Installation of a passenger entertainment audio and video system in the cabin applicable to Dassault Aviation Mystère Falcon 20 aircraft.
- 9. **STC 10031744** Enhanced Mode "S" compliance upgrade applicable to Dassault Aviation Mystère Falcon 20 aircraft.

- 10. **STC EASA.A.S.00306 Rev1 (10031335)** Installation of a multi-functions display Honeywell type KMD-850 applicable to Cessna Citation II model 550 aircraft.
- 11. **STC 10039277** Installation of Patch Iridium Antenna applicable to Dassault Aviation Mystère Falcon 20GF aircraft

These STCs were formerly held by UNI AIR.

Business and Commuter Aircraft holds an EASA approval of procedures demonstrating capability for design (ref. EASA.AP072) and is deemed to be able to undertake the obligations under 21.A.118A and for this purpose, has demonstrated its ability to qualify under the criteria of 21.A.112B of the Annex I (Part 21) to Regulation (EU) No 748/2012.

As a consequence, EASA has accepted the transfer and re-issued the Type Certificate.

## **Former STC reference**

- 1. STC EASA.A.S.03350 (10015037)
- 2. STC 10041337
- 3. STC 10038465
- 4. STC EASA.A.S.03669 (10015241)
- 5. STC EASA.A.S.03349 (10015036)
- 6. STC EASA.A.S.03008 (10014805)
- 7. STC EASA.A.S.03215 (10014951)
- 8. STC EASA.A.S.03546 Rev1 (10015172)
- 9. **STC 10031744**
- 10. STC EASA.A.S.00306 Rev1 (10031335)
- 11. **STC 10039277**

## **New STC reference**

- 1. STC 10015037 Rev. 2
- 2. STC 10041337 Rev. 1
- 3. STC 10038465 Rev. 1
- 4. STC 10015241 Rev. 2
- 5. STC 10015036 Rev. 2
- 6. STC 10014805 Rev. 1
- 7. STC 10014951 Rev. 1
- 8. STC 10015172 Rev. 1
- 9. STC 10031744 Rev. 1
- 10. STC 10031335 Rev. 2
- 11. STC 10039277 Rev. 1

Any Airworthiness Directive (AD) related to these products are still applicable unless replaced or cancelled.

**Contact:** Any request, query or comment shall be sent to:

European Aviation Safety Agency

Attn: Charles Leboeuf Postfach 10 12 53 D – 50452 Köln

E-Mail: <a href="mailto:charles.leboeuf@easa.europa.eu">charles.leboeuf@easa.europa.eu</a>